

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

30-045-25189

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company: BP	Contact: Jeff Peace	
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 326-9479	
Facility Name: Roelofs 4E	Facility Type: natural gas well API No. 3004525189	
Surface Owner: Federal	Mineral Owner: Federal	Lease No. SF-078415

**LOCATION OF RELEASE**

Unit Letter I	Section 22	Township T29N	Range R8W	Feet from the 1800	North/South Line South	Feet from the 790	East/West Line East	County: San Juan
------------------	---------------	------------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------------

Latitude 36.70884 Longitude 107.65732

**NATURE OF RELEASE**

Type of Release: natural gas	Volume of Release: approx. 2014 Mcf of gas	Volume Recovered: no gas recovered
Source of Release: oil dump valve on pent roof separator	Date and Hour of Occurrence: 11:00 PM, 8/25/11-9:00 AM, 10/5/11	Date and Hour of Discovery: 9:00 AM, 10/5/11
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell	
By Whom? Jeff Peace	Date and Hour: 10/6/11 - 2:22 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		RCVD OCT 7 '11 OIL CONS. DIV. DIST. 3
Describe Cause of Problem and Remedial Action Taken.* The oil dump valve on the pent roof separator was stuck in the open position, releasing gas through the valve into the condensate tank. The well has been shut in and in investigation as to the cause of the failure will be done.		
Describe Area Affected and Cleanup Action Taken.* The gas released dissipated into the atmosphere so no clean-up action was possible.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jeff Peace	Approved by District Supervisor: 	
Title: Field Environmental Advisor	Approval Date: 10/11/11	Expiration Date:
E-mail Address: peace.jeffrey@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: October 6, 2011 Phone: 326-9479		

\* Attach Additional Sheets If Necessary

nJK1128655399