



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

ENTERED
10-7-11

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-19-11 Operator Devon API #30-0 45 27341
Property Name NEBU Well No. 560#1 Location: Unit Section 32 Township 3N Range 7E
Well Status(Shut-In or Producing) Initial PSI: Tubing 1180 Intermediate Casing 10 Bradenhead 70

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	-	20		
10 min	0	-	10		
15 min	0	-	10		
20 min	0	-	10		
25 min					
30 min					

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: Braden Head Blew down to 0 psi in
9 min

By Chris Winters
Tester
(Position)

Witness Jerry Mackey

E-mail address

