

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

. 1		(12 3. 2 3. 3. 3. 3.	,		
Date of Test 4/2	28/20	11 Operator	Chevron US	A, Inc.	API #30-0 45-28827
Property Name Horton CB-22 Well No. 1 Location: Unit G: Section 22 Township 32N Range 11W					
Well Status (<u>Producing</u>) Tubing <u>6</u> Intermediate <u>N/A</u> Casing <u>8</u> Bradenhead <u>0</u>					
OPEN BRADENHI	EAD AND	INTERMEDIATE T	O ATMOSPHE	RE INDIVIDUAI	LLY FOR 15 MINUTES EACH
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg		FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE			
TIME 5 min 0	8		Steady Flow_		
10 min 0	8				
15 min <u>0</u>	8		Down to Noth	ing	
20 min			Nothing	XX	<u></u>
25 min			Gas		
30 min			Gas & Water_		
		' '	Water		
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR	FRESH	SALTY	_ SULFUR	BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE REMARKS:					
By Suc N	W	'itness_		000 00 00 00 00 00 00 00 00 00 00 00 00	
(Position) E-mail address					261 81 T18 18 18 18 18 18 18 18 18 18 18 18 18 1