



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX. (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 4/29/2011 Operator Four Star O&G Company API #30-0 45-30514

Property Name Slane Canyon 32 Well No. 1C Location: Unit P Section 32 Township 30N Range 10W

Well Status (Producing) Tubing 120 Intermediate N/A Casing 125 Bradenhead 41

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 min	<1		126			Steady Flow <b>XX</b>	
10 min	<1		127			Surges	
15 min	<1		128			Down to Nothing	
20 min						Nothing	
25 min						Gas <b>XX</b>	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 6 INTERMEDIATE \_\_\_\_\_

REMARKS: The Bradenhead line blew down to a slight constant whisper in 3 seconds.

By Bruce Math

Witness \_\_\_\_\_

(Position)

E-mail address \_\_\_\_\_

