



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

RCVD JAN 4 '12

OIL CONS. DIV.

DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12/16/11 Operator Duane Bentley API #30-0 45-32412-00-X-1
Property Name NEBU Well No. 406A Location: Unit J Section 22 Township 31-N Range 7-W
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 122[#] Bradenhead 2[#]

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	NA	122 [#]		
10 min	0	NA	122 [#]		
15 min	0	NA	122 [#]		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	<u>NO</u>
Surges	<u>NONE</u>
Down to Nothing	<u>1 Secant</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Started test at 11:58 blew down to no pressure
in 1 secant with no fluids. Observed pressures for 15
minutes. Shut in for 5 minutes with no build up on Bradenhead pressure.

By Duane Bentley
Lease operator
(Position)

Witness _____

E-mail address duane.bentley@dvn.com