



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

RCVD DEC 27 '11

OIL CONS. DIV.

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 12-27-11 Operator Burlington Res. API # 30-0 45-34908

Property Name Lively Well # 25M Location: Unit B Sec 29 Twn 30 Rge 8

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas ☒ _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. N/A
Int. Casing Pres. N/A

Pressured annulus up to 560 psi. for 30 mins. Test passed/failed

REMARKS:

No tubing in hole

Budget plug 4025

Need to perform BHT

By [Signature]
(Operator Representative)

Witness

[Signature]
(NMOCD)

Consultant
(Position)

Revised 02-11-02