



NEW MEXICO DEPARTMENT OF CONSERVATION, ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OFF. CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-16-04 Operator CDX Rio, LLC API # 3003923682

Property Name Jicarilla Cont. 148-42 Location: Unit 9 Section 24 Township 25 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 65 Intermediate Casing 65 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH- Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes												
10 minutes												
15 minutes												
20 minutes												
25 minutes												
30 minutes												
5 minute ST												

	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing		
No Flow	X	
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

James Simpson
F.P.S. Tech

(Position)

Witness _____

NMOCD Test Area: