

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-039-22156

OPERATOR

X Initial Report ☐ Final Report

Name of Company: Energen Resources, Inc.	Contact: Ed Hasely
Address: 2010 Afton Place, Farmington, NM 87401	Telephone No: 505-324-4131
Facility Name: Jicarilla L #9	Facility Type: Oil/Gas Well Site

Surface Owner: Jicarilla Apache Tribe	Mineral Owner: Jicarilla Apache Tribe	Lease No. Jicarilla Apache 10
---------------------------------------	---------------------------------------	-------------------------------

LOCATION OF RELEASE

Unit Letter D	Section 10	Township 24N	Range 5W	Feet from the 860	North/South Line North	Feet from the 990	East/West Line West	County Rio Arriba
------------------	---------------	-----------------	-------------	----------------------	---------------------------	----------------------	------------------------	----------------------

Latitude 36.33176

Longitude -107.35342

NATURE OF RELEASE

Type of Release: Condensate Spill	Volume of Release: 131 bbls	Volume Recovered: 0 bbls
Source of Release: Condensate Storage Tank	Date and Hour of Occurrence: 2/22/08	Date and Hour of Discovery: 11:30 am 2/22/2008
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jicarilla EPO – Dixon Sandoval, NMOCD – Brandon Powell, BLM – Kevin Snyder, Bryce Hammond – Jicarilla Oil and Gas	
By Whom? Ed Hasely	Date and Hour: 2/22/2008, 1:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	

RCVD FEB 26 '08

If a Watercourse was Impacted, Describe Fully.* NA



OIL CONS. DIV.
DIST. 3

Describe Cause of Problem and Remedial Action Taken.*

The condensate storage tank appears to have a hole in the bottom allowing the condensate to leak out into the bermed area. No released liquids were able to be recovered. The remaining condensate in the storage tank was removed. The storage tank will be replaced or repaired.

Describe Area Affected and Cleanup Action Taken.* The roads and location are currently very muddy, but once the area dries, plans are to move the equipment so that the soil beneath the equipment can be removed if necessary. Impacted soils will be excavated and transported to a commercial disposal facility. Once the soil is removed, samples will be collected from the excavation and sent to a laboratory for analysis. Upon verification that the samples are below the 100 ppm TPH, the excavation will be backfilled with soil that has been approved by Jicarilla Tribal personnel.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ed Hasely	Approved by District Supervisor: 	
Title: Sr. Environmental Engineer	Approval Date: 2/25/2008	Expiration Date:
E-mail Address: ed.hasely@energen.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/25/08 Phone: 505-324-4131 / 505-330-3584(cell)		

* Attach Additional Sheets If Necessary

nJR 12060 30011

February 25, 2008

RCVD FEB 26 '08

New Mexico Oil Conservation Division
1000 Rio Brazos Road
Aztec, New Mexico 87410
Attn: Brandon Powell

OIL CONS. DIV.
DIST. 3

Re: **Jicarilla L #9**
Initial Release Report Submittal

Dear Mr. Powell:

Enclosed is an initial Release Notification and Corrective Action (C-141) Form for the recent release on the Jicarilla L #9 well location. The release was verbally reported to the Jicarilla EPO, the Jicarilla Oil and Gas, the Farmington BLM, and the New Mexico OCD on the day of the incident. The excavation of impacted soils has been postponed due to the muddy conditions and will take place at a later date. I will follow-up with a final report once the job is complete.

If there are any questions or concerns with this submittal, please contact me at 505-324-4131.

Sincerely,



Ed Hasely
Sr. Environmental Engineer
Energen Resources

Attachment: Final C-141
Lab Reports

Cc: Bert Thomas
Anna Stotts
BLM
Jicarilla EPO
Jicarilla Oil and Gas
HSE File
Facility File
Correspondence