

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

30-039-25787

OPERATOR		X Initial Report	X Final Report
Name of Company Mallon Oil Company	Contact Ron Sansoni		
Address P. O. Box 2797 Durango, CO 81302	Telephone No. (970) 382-9100		
Facility Name Jicarilla 459 No. 8 (O.A.)	Facility Type Gas Well		
Surface Owner Jicarilla Apache Tribe	Mineral Owner		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	20	30N	03W	2205'	FSL	1350'	FWL	Rio Arriba County

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 bbls	Volume Recovered 9 bbls
Source of Release Production Tank	Date and Hour of Occurrence 10/27/00 Night	Date and Hour of Discovery 10/27/00 - 7:30 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Ron Sansoni	
By Whom? Jimmy Costalez	Date and Hour 10/28/00 - 8:10 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The Gas Well began unloading more water than normal, leaving the tank to spill over during the night. A vacuum truck was used to clean up the spill.		
Describe Area Affected and Cleanup Action Taken.* The spill was contained inside the dike. A vacuum truck was used to help cleanup the spill.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION	
Signature: <i>Ronald Sansoni</i>	Approved by <i>Denny Feat</i> District Supervisor: <i>For Frank Chavez</i>
Printed Name: Jimmy Costalez by Ron Sansoni	Approval Date: <i>11/3/00</i> Expiration Date:
Title: Production Foreman	Conditions of Approval:
Date: 10/28/00 Phone: (505) 486-0313	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Not in computer

NSK1217251183