

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131


State of New Mexico

Energy Minerals and Natural Resources Department

Oil Conservation Division

2040 South Pacheco Street
Santa Fe, New Mexico 87505
(505) 827-7131

Form C-141
Originated 2/13/97



Submit 2 copies to:
Appropriate District
Office in accordance
with Rule 116.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report

☒ Final Report

Name: Burlington Resources	Contact: Gregg Wurtz
Address: P.O. Box 4289 Farmington NM 87499	Telephone No.: (505) 326-9537
Facility Name: SAN JUAN 30-6 UNIT 483	Facility Type: Gas Well

Surface Owner: FEE	Mineral Owner: FEE	Lease Number: FEE
--------------------	--------------------	-------------------

LOCATION OF RELEASE

Unit Letter: H	Section: 34	Township: 030N	Range: 006W	Feet From the North/South Line: 1330 north	Feet From the East/West Line: 790 east	County: Rio Arriba
----------------	-------------	----------------	-------------	--	--	--------------------

NATURE OF RELEASE

Type of Release: Produced water (coal seam)	Volume of Release: 15 bbls.	Volume Recovered: 0 bbls.
Source of Release: Pumping unit stuffing box	Date and Hour of Occurrence: 3/13/00 10:00:00 PM	Date and Hour of Discovery: 3/14/00 11:30:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If Yes, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 0	

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

None

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Compressor Plant shut down, well built up pressure and water was forced out stuffing box rubber. Water evaporated and soaked into soils.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

Affected the area around pump jack on location approximately an area 60 x 20 feet, soil moist, no staining of soils was observed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gregg Wurtz</i>	OIL CONSERVATION DIVISION	
Printed Name: Gregg Wurtz	Approved by: <i>Danny G. Joubert</i>	District Supervisor: <i>for Frank Chavez</i>
Title: Environmental Representative	Approval Date: <i>3/22/00</i>	Expiration Date:
Date: Phone: (505) 326-9537 or (505) 326-9841	Conditions of Approval:	Attached: <input type="checkbox"/>

Not in computer

NJK1217336149