



### BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-24-04 Operator C.D.X. Rio LLC API # 3003906593

Property Name Jic Apache 102 #12 Location: Unit G Section 9 Township 26 Range 4  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 160# Intermediate \_\_\_\_\_ Casing 190# Bradenhead 0#

**OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH**


Time	Bradenhead			Intermediate		Flow Description	Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor			
5 minutes	<u>0</u>					Steady Flow		
10 minutes						Surges		
15 minutes						Down to Nothing		
20 minutes						No Flow <u>-X</u>		
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute St						Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 0# Intermediate \_\_\_\_\_

REMARKS:



by Harry Watson  
Tech T.P.S  
(Position)

Witness Darrell Spear T.P.S