



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-23-04 Operator C.D.X. Rio LLC API # 3003906709

Property Name Jir Apache 102 #7 Location: Unit G Section 3 Township 26 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 0 Intermediate Casing 120 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>					Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing <u>X 155 sec</u>	
20 minutes						No Flow <u>-X</u>	
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute St						Water	


If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

Tubing too low too gauge



by

Harry Whitson

Tech T.P.S

(Position)

Witness

Donald J. T.P.S

NMOCD Test Area: