



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-25-12 Operator CHEVRON MIDCONTINENT, LP API # 30-030-045-28794
Property Name KLINE 10 #3 Well No. #3 Location: Unit Section -10 Township -31N Range -13W
Well Status (Shut-In or Producing) Initial PSI: Tubing 6.8 Intermediate X Casing 6.2 Bradenhead 0.2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	Y	6.2		
10 min	0	Y	6.2		
15 min	0	Y	6.2		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

Oil Cons. Div
District III

JUL 05 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.1 INTERMEDIATE

REMARKS:

By Randy CalcoTE
Calder services
(Position)

Witness

E-mail address Randy.c@calder services.com