



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://nemnr.state.nm.us/ocd/District III/3distric.htm](http://nemnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 12-8-04 Operator SCHALK DEVELOPMENT API #30-0 39-20799
Property Name SCHALK 52 Well No. 3 Location: Unit E Section 24 Township 29 Range 5
Pressure(Shut-In or Producing) Tubing 138 Intermediate _____ Casing 156 Bradenhead 70

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>156</u>	Steady Flow <u>XX</u>	
10 minutes		<u>156</u>	Surges _____	
15 minutes		<u>156</u>	Down to Nothing _____	
20 minutes		<u>156</u>	Nothing _____	
25 minutes		<u>156</u>	Gas <u>XX</u>	
30 minutes		<u>156</u>	Gas & Water _____	
			Water _____	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

REMARKS:

BRADENHEAD STILL had slight blow out 1"
VALVE AFTER 30 MINS.

By SCOTT RODGERS

Witness

Jack Evans

FIELD TECH

(Position)