



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrnd.state.nm.us/ocd/District III3district.htm](http://emnrnd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 7-6-04 Operator Koch Exploration API #30-0 4531394
Property Name Susan B Co Well No 34-1A Location: Unit J Section 34 Township 28N Range 10W
Well Status(Shut-In or Producing) Tubing _____ Intermediate _____ Casing _____ Bradenhead 3rd

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes			Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing ☒	
20 minutes			Nothing	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS: Baseline Bradenhead Test. Cement had not come to surface
on long string job. Bradenhead ~~flow~~ blow dead in 3 seconds.

By Kenneth Cough
Ringer
(Position)

Witness _____

