

(Position)

NEW MEXICO ENERGY, MINIERALS / & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test_	9-21-04	Operator	Mallon Oil	API #30-0 39 -	26234
Property Nam	eJicanla 464	Well No &	Location: Unit K	Section 29 Townsh	nip 30N Range 3W
Well Status(S	hut-In or Producing	g) Tubing 27	Intermediate Ma Cas	ing 71 Bradenhe	ad 🗷
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH					
TIME	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Flow		
10 minutes		·	Surges	·	
15 minutes			Down to Nothin	ng	
20 minutes	·		Nothing		
25 minutes	-		Gas		
30 minutes			Gas & Water_		
			Water		
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR	RFRESH	SALTY	SULFURBLA	ACK .	5723433
5 MINUTE SH	UT-IN BRADENH	EAD	INTERMEDIATE	— <u>1877</u> 92	o Porting
REMARKS:				· [50] - [5]	
					<u> Cornello II</u>
					0,0
	<i></i>				
By	+ DV	Witn	ess		
Lea	u Oprator				