



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

RCVD JUL 23 '12
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-23-12 Operator Burlington Res API #30-0 45-29450

Property Name MURPHY Well No. 0#4A Location: Unit L Section 27 Township 30 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate V/A Casing 239 Bradenhead 18.4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>239</u>		
10 min	<u>0</u>		<u>239</u>		
15 min	<u>0</u>		<u>239</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>/</u>	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD .8

INTERMEDIATE V/A

REMARKS:

BH, 0 on drager tube - light at 1 minute - vapors
at 2 min. dead at 3 min.

By [Signature]

Witness [Signature]

(Position)

E-mail address _____