



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

RCVD JUL 23 '12

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV.

DIST. 3

Date of Test 7-23-12 Operator Buckington API #30-0 45-30910

Property Name Federal A Well No. 1M Location: Unit 37 Township 30 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 117 Intermediate 391 Casing 392 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	742	391	14	396
10 min	0	739	395	1.5	397
15 min	0	741	396	0	397
20 min				-0	398
25 min				-0	398
30 min				-1	398

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS

BH Nothing when opened -

BH On casing tube

Int. Gas Sample taken - Blue gas just 30 seconds -

By _____

Witness _____

(Position)

E-mail address _____

Vacuum at 20 min.

Test incomplete
Pressure
Washing bit
every thing