

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
811 S. First St, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

**REVISED**

☒ Initial Report

☐ Final Report

Name of Company	Dugan Production Corp.	Contact	Rodger Mullins
Address	P O Box 420, Farmington, NM 87499-0420	Telephone No.	505-326-4548
Facility Name	Clementine Com #90	Facility Type	Gas Well*

Surface Owner	Federal	Mineral Owner	Federal	API No.	30-045-34015
---------------	---------	---------------	---------	---------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	27	24N	10W	1285	South	1185	West	San Juan

Latitude 36.28083 Longitude 107.88853

**NATURE OF RELEASE**

Type of Release	Produced Water	Volume of Release	<10 bbls	Volume Recovered	None
Source of Release	Wellhead	Date and Hour of Occurrence	6-26-12 in morning	Date and Hour of Discovery	6-06-12 @ 0900
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Brandon Powell - NMOCD & Bill Liess - BLM		
By Whom?	Rodger Mullins	Date and Hour	6-26-12 1030 hrs		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*	RCVD JUL 3 '12 OIL CONS. DIV.
---	----------------------------------

Describe Cause of Problem and Remedial Action Taken.*	DIST. 3
Wellhead kill was broken off, possibly by horses. When spill area dries up, gypsum will be raked into the dirt.	

Describe Area Affected and Cleanup Action Taken.*
Water pumped out onto the ground, mainly in front of the wellhead. Water soaked in quickly.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>		OIL CONSERVATION DIVISION	
Printed Name: Rodger Mullins		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Production Foreman		Approval Date: <u>7/06/2012</u> Expiration Date:	
E-mail Address: rmullins@duganproduction.com		Conditions of Approval:	
Date: June 26, 2012 Phone: 505-325-1821		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

nJK1218853093