



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1008 RIO BRAZOS ROAD
AZTEC NM 87410
(808) 334-6170 FAX: (505) 334-6170
[http://emrwd.state.nm.us/ocd/District III/3distrct.htm](http://emrwd.state.nm.us/ocd/District%20III/3distrct.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 9-8-04 Operator Pue API #30-0 39-27294

Property Name Lineon Well No. 11P Location: Unit 1 Section 6 Township 26N Range 6W

Well Status (Shut-In or Producing) Producing Tubing 43 Intermediate 7 Casing 78 Bradenhead X

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>TSTM</u>	<u>78</u>	Steady Flow	
10 minutes	<u>TSTM</u>	<u>78</u>	Surges	
15 minutes	<u>TSTM</u>	<u>78</u>	Down to Nothing	<u>X</u>
20 minutes	<u>TSTM</u>	<u>78</u>	Nothing <u>X</u>	
25 minutes	<u>TSTM</u>	<u>78</u>	Gas	<u>X</u>
30 minutes	<u>TSTM</u>	<u>78</u>	Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE

REMARKS:

Intermediate Blow Down to Nothing 22 seconds

By A. Lucio
Pumper
(Position)

Witness Jan Carney

