



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-29-12 Operator XTO Energy API #30-0 45-28825
Property Name Polco Fee FC 15 Well No. 2 Location: Unit 6 Section 15 Township 29 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 23 Intermediate N/A Casing 38 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>38</u>		
10 min	<u>0</u>		<u>38</u>		
15 min	<u>0</u>		<u>38</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	<u>DIST. 3</u>
Down to Nothing	
Nothing	<u>OIL CONS. DIV.</u>
Gas	<u>RCVD AUG 29 '12</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

H₂S test performed. No H₂S detected.
Nothing when opened.

By Doug Simon
LEASE OPERATOR
(Position)

Witness Mouca Kuchling

E-mail address _____