



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 9/24/2010 Operator Chevron Midcontinent, L.P. API #30-0 39-06954

Property Name RINCON UNIT Well No. 160 Location: Unit N Section 23 Township 27N Range 06W

Well Status (Producing) Tubing 30 Intermediate N/A Casing 42 Bradenhead <1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

| Testing TIME | PRESSURE | | | | |
|-----------------|----------|-----|-----|-----|-----|
| | BH | Int | Csg | Int | Csg |
| 5 min | 0 | | 42 | | |
| 10 min | 0 | | 42 | | |
| 15 min | 0 | | 42 | | |
| 20 min | | | | | |
| 25 min | | | | | |
| 30 min | | | | | |

| FLOW CHARACTERISTICS | |
|----------------------|--------------|
| BRADENHEAD | INTERMEDIATE |
| Steady Flow | |
| Surges | |
| Down to Nothing | XX |
| Nothing | |
| Gas | XX |
| Gas & Water | |
| Water | |

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS: The Bradenhead valve blew down to nothing in 2 seconds.

By Bruce Martin
by April E. Pohl
(Position)

Witness _____

E-mail address _____

Oil Cons. Div
District III

JUL 20 2012