



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5/16/2010 Operator Four Star Oil & Gas API #30-0 39-20500

Property Name RINCON UNIT Well No. 193 Location: Unit K Section 35 Township 27N Range 07W

Well Status (Producing) Tubing 37 Intermediate N/A Casing 49 Bradenhead *

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow _____

Surges _____

Down to Nothing _____

Nothing _____

Gas _____

Gas & Water _____

Water _____

DENIED

BY: Brandon Powell
DATE: 7/10/12 (505) 334-6178

Test required by 11/12/12

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

Oil Cons. Div
District III

JUL 20 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS: *BH valve stem is broken off, needs replaced.

By Bruce Martin
by April E. Pohl
(Position)

Witness _____

E-mail address _____