

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 5/24/12 Operator Dugan Production Corp. API # 30-045-29288  
Property Name FLO JO Well No 6 Location: Unit K Section 1 Township 23N Range 11W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 40 Intermediate N/A Casing 40 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	Ø		40			
10 minutes	Ø		40			
15 minutes	Ø		40			
20 minutes	Ø		40			
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	✓	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By WJ 98  
\_\_\_\_\_  
Switcher  
(Position)

Witness \_\_\_\_\_