## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Road

Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 0 1 2012

												110				
Date of Test	6-13	3-12	_ Oper	tor	Dugan Production		n Corp.		API#	30-045	-		9W			
Property Name DECEMBER DREAM					Well No_	3	_Location Unit		K	Section	7	Township		23N	Rang	ge .
Well Status(Shut-In or Producing) Initial PSI:					Tubing <u> </u>			te		_Casing	4.0	-/	Bradenh	ead	0	•
					_			_								
OPĖN BŘAI	DENIH	=ΔΏ ΔΛ	דואו חו	ERME	:DIATE T	ΓΩ ΔΤΜΩ	SPHERE	ואוטוא	المالالمار	I V EOR	15 1	AINII ITES I	=ACH			
OF EN BIXA			SURE		-DIATE I	I O ATMO	OI TILIXL	IIVDIV	IDOAL	LITOR	1010	IIIVOTEST				
Bradenhead Interm									FLOW	CHARAC <sup>-</sup>						
TÌME	вн	Int Csg	Int	Csg	_		_		BRADI	NHEAD	_	INTERME	DIATE	-		
5 mintues	Q.	44			;	Steady Flov	v _							_		
10 minutes	6	44			] ;	Surges								_		
15 minutes	0	ui			$\Big]$ ,	Down to No	thing _									
20 minutes	0	44				Nothing								•		
25 minutes						Gas	_							_		
30 minutes			<u> </u>		<u> </u>	Gas & Wate	er _							_		
				•		Water	_									
										•						
<u>if bradenh</u>	ead fl	owed	<u>water</u>	, che	ck all of	f the des	<u>scription</u>	s tha	t appl	y below	<u>/:</u>					
		CLEA	R		FRESH		_SALTY _		SULFU	IR	BLAC	K				
									-				-			
5 MINUTE S	SHUT-I	IN	BRA	DĖNHE	AD -	.0	_	INTERI	MEDIATI	Ē	_	_				
REMARKS.																
							****									
	<u> </u>			<u>:-</u>					<del></del>			<del></del>		-		
			<del></del>		<u> </u>	<u>,</u>										
									<del></del>		_			-		
	110		One	1	#4	10										
Ву	por	<u></u>	C:		-11 (		_	Witnes	s					-		
			(Posi	tcher tion)			_									