NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX-(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 0 1 2012 Date of Test (p-/9-/7 Operator Dugan Production Corp. API # 30-045-33172
 Well No.
 1
 Location: Unit
 D
 Section
 3
 Township
 30N
 Range
 14W
 Property Name HIGH FINANCE Well Status (Shut-In or Producing) Initial PSI: Tubing 50 Intermediate Casing 65 Bradenhead OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH **PRESSURE** Bradenhead Interm **FLOW CHARACTERISTICS** TIME Int Csg Int **BRADENHEAD** INTERMEDIATE 5 mintues Steady Flow 10 minutes Surges Ø 15 minutes Down to Nothing 20 minutes Nothing 25 minutes Gas 30 minutes Gas & Water Water If bradenhead flowed water, check all of the descriptions that apply below: CLEAR ________ FRESH _______ SALTY _______ SULFUR _______ BLACK _______ **5 MINUTE SHUT-IN** BRADENHEAD INTERMEDIATE REMARKS:

Witness

Ву

Switcher (Position)