

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3

NOV 0 1 2012

						•					IAO A	U E -	
Date of Test	6-6-	- 12	Operator	Dugan Production (ion Corp.		API #	30-045-29465				
Property Name		HUERF/	OTINA	_Well No	5E	Location: Unit		J	_Section _	10 Township		26NRan	Rang
Well Status(Shu	ut-In or(P	roducing)	Initial PSI.	Tubing	B	Intermedia <u>te</u>			_Casing _	300		_Bradenh <u>ead</u>	
OPEN BRAI	DENHE	AD ANI		EDIATE '	TO ATM	OSPHERE	E INDIV	IDUAL	LY FOR	15 M	INUTES	EACH	
	Bradenhead Interm							FLOW CHARACTER			RISTICS		
TIME	-	nt Csg	Int Csg	_				BRADE	ENHEAD		INTERME	DIATE	,
5 mintues	Ø	300		_	Steady Flo	ow							
10 minutes	×	300			Surges						*		
15 minutes	УŚ	500		Down to Nothing									
20 minutes	Ø	300		1	Nothing	-		X					
25 minutes	Ø	300		1	Gas								
30 minutes	Ø	300		1	Gas & Wa	iter	-						
	', 	•	•	-	Water			• •					
		•			• • •	•							
<u>If bradenh</u>	ead flo	owed w	<i>t</i> ater, che	ck all o	the de	escription	ns tha	t appl	y below	<u>/:</u>			
		CLEAR		_FRESH		SALTY		SULFU	IR	BLAC	<	_	
5 MINUTE S	HUT-IN	N	BRADENHE	AD .	Ø	_	INTERN	/IEDIATE			_		
REMARKS:				2	•								
	·	_/	January J.	/							<u> </u>		,
	a de la companya de l	<u>"</u>	A SEE SEE	•			·			•	·		•
	get and a second		is in the second se										
	<u></u>				-ALLIAN	ng gad radich is the first							•
ву (A STATE OF THE STA						Witness	:					
"		-	Switcher			_	***************************************						
A Part of the same			(Position)										
L													