NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

							•			# 5015	
Date of Test	6-12-12	Operator	Dugan	Production	on Corp.	API#	30-045	-349	83		
Property Name	e MARTINEZ BI	EGAY COM	Well No	1	_Location: Uni	t <u>P</u>	Section	34	Township	24N	Range 10W
Well Status(SI	nut-In or Producing)	Initial PSI:	Tubing	83	Intermediate		Casing	<u> </u>	5	_Bradenh	ead O
<u> </u>					·						
ODEN RRA	.DENHEAD AND	NITEDME	DIATE	TO ATMO	SDHEDE IN	חו/וחו ואו	I V EOR	15 M	IINII ITES I	EACH	
OPEN DIVA	PRESS		DIAIL	TO ATMC	OFFILINE IN	DIVIDUAL	LIION	13 10	IIINOTES	LACIT	
	Bradenhead Interm					FLOW	CHARAC'	ACTERISTICS			
TIME	BH Int Csg	Int Csg	_			BRADI	ENHEAD		INTERME	DIATE	
5 mintues	0 75			Steady Flov					_		
10 minutes	0 35		1	Surges							
	0 35		1				_				
15 minutes			1	Down to No							
20 minutes	0 35	<u> </u>	1	Nothing							
25 minutes			-	Gas							
30 minutes				Gas & Wate	er						
				Water							
l e la cardonal			-111 -	£ 41							
<u>ir bradeni</u>	nead flowed w	ater, cne	ck all o	itne des	scriptions	tnat appi	y below	<u>/:</u>			
	CLEAR		FRESH		_SALTY	SULFU	IR	BLAC	κ <u> </u>	_	
				_							
	SHUT-IN	BRADENHE	AD		INT	ERMEDIATE	Ē		_		
REMARKS:							-				
	<u></u>										
,	· · · · ·			*	,					<u>_</u>	
	, 16	1	£111								
Ву	Mula	my x			_ · Wit	tness					
		Switcher			_						

(Position)