

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 01 2012

Date of Test 5-22-12 Operator Dugan Production Corp. API # 30-045-22937
Property Name BLANCO WASH Well No 5 Location: Unit L Section 1 Township 24N Range 9W
Well Status(Shut-In or Producing) Initial PSI: Tubing 40 Intermediate Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		35			
10 minutes	0		35			
15 minutes	0		35			
20 minutes	0		35			
25 minutes	0		35			
30 minutes	0		35			

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow	X	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD X INTERMEDIATE

REMARKS:

By

Mike Smeal

Witness

Switcher

(Position)