

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3/district.htm>

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address) **OIL CONS. DIV DIST. 3**

NOV 01 2012

Date of Test 5-08-12 Operator Dugan Production Corp. API # 30-045-32991  
Property Name SALGE FEDERAL A COM Well No. 90S Location: Unit J Section 3 Township 25N Range 13W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 70 Intermediate N/A Casing 4 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes	0		4		
10 minutes	0		4		
15 minutes	0		4		
20 minutes	0		4		
25 minutes	0		4		
30 minutes	0		4		

FLOW CHARACTERISTICS

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

BRADENHEAD	INTERMEDIATE

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Travis Brearton #38  
Switcher  
(Position)

Witness \_\_\_\_\_