NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

?

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 0 1 20 ...

Date of Test	7-10-	10	Operator	Dugar	Productio	n Corp.		_API#	30-045	-3452	3		_	
Property Name														11W
Well Status(Sh	ut-In or Prod	ucing)	➤ Initial F	PSI. Tubing	128	_Intermedi	ate N	la	Casing	28		Bradeni	nead (D
				· · · · · · · · · · · · · · · · · · ·								-		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH PRESSURE Bradenhead Interm FLOW CHARACTERISTICS														
TIME	BH Int Csg Int Csg			sg	-							DIATE	_	
5 mintues	0			28	Steady Flow	/								
10 minutes	0		2	8	Surges								_	
15 minutes	0		Q	18	Down to Not	thing							-	
20 minutes					Nothing			~					_	
25 minutes					Gas							-	_	
30 minutes				Ī	Gas & Wate	r							_	
	 				Water								_	
If bradenhead flowed water, check all of the descriptions that apply below:														
	C	CLEAR		FRESH		SALTY		SULFU	R	BLACK		_		
5 MINUTE S	HUT-IN		BRADE	VHFAD	0		INTERN	MEDIATE	.		OIL C	CONS. I	ום עוכ	ST. 3
REMARKS:			DIVIDE!	11 12/10		-	IIVI EIKI	VICDIATE				NOV 0	1 2012	•
		<u>.</u>			<u></u> ,			··				MOA A	. ZUIZ	
<u></u>													_	
	 .			<u> </u>									_	
<u></u>							<u></u>						_	
			_											
Ву	KEN	Ny	Sel	MANUE		_	Witness	·					_	
			Switch			_								
			(Position	1)										