



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3distrctc.htm](http://emnrd.state.nm.us/ocd/District%20III/3distrctc.htm)

**BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test September 30, 03 Operator M&M PROD. OPER API #30-0 39-05559

Property Name CUTLER Well No. #5 Location: Unit I Section 10 Township 24N Range 06W

Well Status(Shut-In or Producing) Tubing 2 1/2 Intermediate 0 Casing 110 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes			Steady Flow	
10 minutes			Surges	
15 minutes	✓	✓	Down to Nothing	
20 minutes			Nothing	✓
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS:



By Aberto Harvey

Witness \_\_\_\_\_

Pumper  
(Position)