

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

## BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test October 13,03	Operator	M&M PROD.OPE	RAPI #30-0 <u>39</u>	-05257
Property Name JICARILLA A	BELWell No. #	Location: Unit AS	Section <u>31</u> Townsl	hip <u>244</u> kange <u>04</u> W
Well Status(Shut-In or Producin	g) Tubing 7/	Intermediate O Casi	ng <u>89</u> Brandenl	head_O_
OPEN BRADENHEAD AND I	NTERMEDIATE	TO ATMOSPHERE INDIV	VIDUALLY FOR 15	MINUTES EACH
PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		Steady Flow		
10 minutes		Surges		
15 minutes	V	Down to Nothin	ng	
20 minutes		Nothing		,
25 minutes				
30 minutes				
If bradenhead flowed water, check a	all of the descriptio			
	•	SULFUR BLA	CK	
, ·			18 19	20 21 22 23
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE				
REMARKS:				2000
		<u> </u>		SON ST
			601	9.5 ½ £ 1.2 × 2.0
			- Vec	957.60
By Alonso Harry	Wit	mess		
By Alonzo Harry  Plemou  (Position)				