

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District.III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test Ochher 28,03	Operator Benson - Mondin - Gr	API #30-0 45 -	13305
Property Name foster, Riddle Wel	l No Location: Unit	t <u>P</u> Section <u>/3</u> Townsh	nip <u><i>25-N</i>Range_8-W</u>
Well Status(Shut-In or <u>Producing</u>) Tub	oing 60 Intermediate 0	Casing 70 Brandenl	nead
OPEN BRADENHEAD AND INTERME	EDIATE TO ATMOSPHERE	INDIVIDUALLY FOR 15	MINUTES EACH
PRESSURES: TIME INTERMEDIATE CA	SING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	Steady Flo	ow	
10 minutes	Surges_		
15 minutes	Down to 1	Nothing .	
20 minutes	Nothing_		1
25 minutes	Gas		
30 minutes	Gas & W	ater	
	Water		7720772
If bradenhead flowed water, check all of the	descriptions that apply below:		No. 3
CLEAR FRESH SA	LTYSULFUR	BLACK E	8 4 200 m
5 MINUTE SHUT-IN BRADENHEAD REMARKS:	INTERMEDIATE		95481
			
By	Witness		
(Position)			