



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 7-22-03 Operator Merrion Oil & Gas API #30-0 45-30881

Property Name Serendipity Well No. 5 Location: Unit F Section 26 Township 24N Range 13W

Well Status(Shut-In or Producing) Tubing 7 Intermediate NA Casing 14 Bradenhead X

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>NA</u>	<u>14</u>	Steady Flow	<u>NA</u>
10 minutes		<u>14</u>	Surges	
15 minutes		<u>14</u>	Down to Nothing <u>Nothing</u>	
20 minutes		<u>14</u>	Nothing	
25 minutes		<u>14</u>	Gas	
30 minutes		<u>14</u>	Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD X INTERMEDIATE NA

REMARKS:

This is a re-test. I had left the CSE & tub pressure blank at top of page. This is a pumping well with a compressor pulling on CSE from 1/2 mile away. Bradenhead was plumbed above ground when well was drilled - Bradenhead completely dead.

By Alfred Reisel
Contract Pumping
(Position)

Witness _____

