

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-1-03 Operator Dugan Production Corp. API # 30-045-29465
Property Name HUERFANITO Well No. 5E Location: Unit J Section 10 Township 26N Range 09W
Well Status(Shut-In or Producing) Tubing 75" Intermediate N Casing 150" Bradenhead 0"

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	<u>N</u>		Steady Flow	<u>Nothing</u>	<u>N</u>
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR N FRESH N SALTY N SULFUR N BLACK N

5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE N

REMARKS:

well has piston was flowing on Delay during Test

By

19

Switcher
(Position)

Witness