

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 384-678 FAX: (805) 334-6170
http://emard.state.mm.us/ocd/District IM/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 9-25 - 03	Operato	Roddy Production Co. Al	PI #30-0 <u>45 - 2</u>	.9812
Property Name Newsom		00 Location: Unit 6 Secti		
Well Status(Shut-In or Producing	g) Tubing O	Intermediate N/A Casing I	OO Brandenh	ead_O_
OPEN BRADENHEAD AND IN	NTERMEDIATE '	TO ATMOSPHERE INDIVIDU	JALLY FOR 15	MINUTES EACH
PRESSURES: TIME INTERMEDIATE	CASING		ADENHEAD LOWED	INTERMEDIATE FLOWED
5 minutes N/A	100	Steady Flow		
10 minutes	100	Surges		
15 minutes	100	Down to Nothing		
20 minutes		Nothing		
25 minutes		Gas		
30 minutes		Gas & Water	ACT.	272820
•		Water		
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH	SALTY	SULFUR BLACK		3
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE				
REMARKS: Pumpia	ck on	location - prod	lucina	<u>Casina</u>
1/1		a repairs	٦	J
		2 .		
`				
By fin Mikemy	₹ Wi	tness		
				·