

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

Date of Test 9/21/03 Operator Dugan Production Corp. API # 30-045-28619  
Property Name MCDUGALL Well No. 2 Location: Unit I Section 09 Township 23N Range 10W  
Well Status(Shut-In or Producing) (Producing) Tubing 10 Intermediate NA Casing 10 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing	X	
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_


**5 MINUTE SHUT-IN**

BRADENHEAD \_\_\_\_\_

INTERMEDIATE \_\_\_\_\_

REMARKS:

By



Witness \_\_\_\_\_

38

Switcher  
(Position)

