

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.rm.us/ocd/District iii/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 6 11 03 Operate	or Kach Exploration COLUC API #30-045-28111
Property Name Christina 30 Well No. Location: Unit M Section 30 Township 28 Range 10 W	
Well Status(Shut-In or Producing) Tubing 2	Intermediate Casing 9 BrandenheadO
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURES: TIME INTERMEDIATE CASING	BRADENHEAD INTERMEDIATE FLOWED FLOWED
5 minutes	Steady Flow
10 minutes	Surges
15 minutes	Down to Nothing
20 minutes	Nothing Nothing
25 minutes	Gas
30 minutes	Gas & Water
Water Water	
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE	
REMARKS: Well has no intermediate casing	
By Slenn K Ituo Wi	itness
By Slenn R Ital Winger (Position)	