

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District lii/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test_	6-19-03	Operator	WPX	_API #30-0 <u>39</u>	2947700
Property Nam	ne Rosa	_Well No. <u>338</u>	Location: Unit K	Section <u>32</u> Townsh	nip <u>32W</u> Range <u>6W</u>
Well Status(Shut-In or Froducing) Tubing 76 Intermediate N/A Casing 76 Brandenhead 2					
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH					
TIME	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	NA		Steady Flow		NA
10 minutes_)		Surges		
15 minutes			Down to Nothin	g 3 Sec.	
20 minutes			Nothing		
25 minutes		· · · · · · · · · · · · · · · · · · ·	Gas		
30 minutes		***************************************	Gas & Water		
			Water	1734	56
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY SULFUR BLACK					
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE					
REMARKS: Bradenhead had 2 lbs, Blew down to Nothing in 3 sec.					
(Loft DOEN)					
By Mark Schwellman Witness					
Positi	ch.	 .			•