



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 6/10/03 Operator Koch Exploration Co., LLC API #30-0 45-27983

Property Name Gardner C Well No. 2 Location: Unit 6 Section 31 Township 32N Range 8W

Well Status (Shut-In or Producing) Tubing 2 1/2 Intermediate - Casing 19 Bradenhead 5 #

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		19 #	Steady Flow	
10 minutes		19 #	Surges	
15 minutes		19 #	Down to Nothing <u>X</u>	
20 minutes		19 #	Nothing	
25 minutes		19 #	Gas <u>X</u>	
30 minutes		19 #	Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR - FRESH - SALTY - SULFUR - BLACK -

5 MINUTE SHUT-IN BRADENHEAD 0 # INTERMEDIATE -

REMARKS:

~~Bradenhead~~ Bradenhead Blew Down in about
5 Seconds

By Kenneth Cash
Pumper
(Position)

Witness -

