

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Off Conservation division
AZTEC DISTRICT OFFICE
1000 FIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Property Name S. mmons Well Status (Shut-In or Producing	Well No. <u>E</u>	-Z_Location: Unit	Section 23 Towns	hip 29 Range 9
OPEN BRADENHEAD AND IN	TERMEDIATE	TO ATMOSPHERE INDIV	VIDUALLY FOR 15	MINUTES EACH
PRESSURES: TIME INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	·	Steady Flow		
10 minutes		Surges		
15 minutes		Down to Nothing	5	
20 minutes		Nothing	<i>\lambda</i>	
25 minutes		Gas		
30 minutes		Gas & Water	· · · · · · · · · · · · · · · · · · ·	•
	٠	Water		<u></u>
If bradenhead flowed water, check all	of the description	s that apply below:		_
CLEAR FRESH 5 MINUTE SHUT-IN BRADENHE. REMARKS:			MAY!	23
By KenWarchester Field Tech (Position)	Witne	SS		