



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-16-05 Operator Roddy Productive API #30-0 45-30293
Property Name OweU Well No. 2A Location: Unit C Section 19 Township 31 Range 12
Well Status (Shut-In or Producing) Tubing 29 Intermediate 44 Casing 143 Bradenhead 90

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>143</u>	Steady Flow	
10 minutes	<u>0</u>		<u>143</u>	Surges	
15 minutes	<u>0</u>		<u>143</u>	Down to Nothing <u>X</u>	
20 minutes				Nothing	
25 minutes				Gas <u>X</u>	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 10 INTERMEDIATE _____

REMARKS:

Braden head blew down in less than 30 sec.

By Jeremy Duane
Operator
(Position)

Witness _____

E-mail address _____

