## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

d		Sundry Notices and B	/		
		7005 JUL	5 PM 2 25	5.	<b>Lease Number</b> BIA #14-20-603-734
•	pe of Well Well	·	RECEIVED ARMINGTON NM	6.	If Indian, All. or Tribe Name Navajo
2. Na	me of Operator			7.	Unit Agreement Name Horseshoe Gallup
Vı	ulcan Minerals & Energy, o	e/o NMOCD Aztec Distri	ct Office	10772×8.	Well Name & Number
3. Address & Phone No. of Operator 1000 Rio Brazos Road, Aztec, NM 87410			78 8 0	200 - 9\	HSGU #58 API Well No.
4. Lo	cation of Well, Footage, S	ec., T, R, M		10	30-045-10198  Field and Pool  Horseshoe Gallup
19	980' FNL and 1980' FEL, Se	ction 31, T-31-N, R-16-W		2.72 January 171.	County & State San Juan County, NM
	IECK APPROPRIATE BOX pe of Submission	TO INDICATE NATURE Type of Action	OF NOTICE, REPOR	T, OTHER D	ATA
ıy	Notice of Intent	X Abandonment	Change of Pl		
	X Subsequent Report	Recompletion Plugging Back	New Constru Non-Routine		
	Subsequent Report	Casing Repair	Water Shut of		
	Final Abandonment	Altering Casing Other -	Conversion t		
6/20/0	A-Plus Well Service Plu Purchase Agreement: 4  MOL and RU rig. Check hot oil rods and tubing wi	15210700028; Purchas well pressures: light blow	se Document: 05-19	99-000441. ng, 20# on tul	bing. Unseat pump and
6/21/0	5 MOL and RU. ND wellhe	•	·	·	
6/22/0	Round trip 4.5" casing scraper and A+ workstring to 999', unable to get deeper. TIH with 4.5" DHS CR and set at 979'. Circulate well clean with 16 bbls of water. Pressure test 4.5" casing to 500#, held OK. Sting into CR and establish rate 1 bpm at 800#. Plug #1 with CR at 979', mix and pump 44 sxs Type III cement (58 cf), squeeze 28 sxs under CR and leave 12 sxs above the CR up to 648' to isolate the Gallup interval. TOH and LD all tubing. Perforate 3 holes at 149'. Establish circulation out the bradenhead with 18 bbls of water. Wait for oil to separate in annulus. Plug #2 with 47 sxs Type III cement (62 cf) pumped down the 4.5" casing from 149' to surface, circulate good cement out the bradenhead. Shut in well and WOC. ND BOP. Dig out and cut off wellhead. Found cement at the surface in the 4.5" casing and in the annulus. Mix 15 sxs cement to fill casing and install P&A marker. RD and MOL. D. Davis, NMOCD, was on location.				
SIGNA		Con	tractor	June 23, 2	
	William F. Clark				ACCEPTED FOR RECORD
(This s	pace for Federal or State Of	fice use)			JUL 0 8 2005
	OVED BY	Title y:	and an extended a fill the same special and a	<u></u>	FRAMANGTON FIELD OFFICE BY
					NMOCD