

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY LP

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1450'FNL, 1190'FEL, Sec.16, T-31-N, R-11-W, NMPM, San Juan County

API # (assigned by OCD)

30-045-10770

5. Lease Number

6. State Oil&Gas Lease #

B-11017-28-NM

7. Lease Name/Unit Name

Brookhaven Com G


8. Well No.

9

9. Pool Name or Wildcat

Basin Dakota/Blanco Mesaverde

10. Elevation:



Type of Submission

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment

Type of Action

☐ Abandonment

☒ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

It is intended to recompleate the subject well according to the attached procedures.

SIGNATURE Frances Bend Regulatory Specialist July 5, 2005

FSB

(This space for State Use)

Approved by

STATE OIL & GAS INSPECTOR, DIST. 63

Date

JUL - 6 2005

HOLD C104 FOR Plat For MV and the order

Brookhaven Com G #9 Sundry Procedure

Unit H, Section 16, T31N, R11W

1. MIRU completion rig. TOOH with tubing.
2. Pressure test casing to 3500 psi for 15 minutes.
3. Perforate and fracture stimulate the Point Lookout and Lower Menefee formations.
4. Flow back well. Clean out as required.
5. Mill out cast iron bridge plug above the Dakota to restore.
6. Land tubing. RDMO rig.
7. Return well to production as a Mesaverde-Dakota commingled producer.