

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Property Name <u>South</u> Well Status (Shut-In or			•		1
			ATMOSPHERE INDIV		
	PRESSURES:	CASING		BRADENHEAD FLOWED	INTERMEDIAT FLOWED
5 minutes	NONE	0	Steady Flow		
10 minutes			Surges		,
15 minutes			Down to Nothin	g	
20 minutes		0	Nothing	V	NONE
25 minutes	<u> </u>		Gas	,	· · · · · · · · · · · · · · · · · · ·
30 minutes			Gas & Water		
			Water	·	
If bradenhead flowed wa	ter, check all of the d	escriptions t	hat apply below:	18	
CLEAR	FRESH SAI	TY	SULFUR BLAC	K	
5 MINUTE SHUT-IN	BRADENHEAD		INTERMEDIATE		•
REMARKS:			INTERNEDIATE		
				18 mg	
By Get Dute	aug		Witness		
	//				
Pumper (Position)					