

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM\87410

(505) 334-6178

FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Well Status (Shut-In	or Producing) Tubi	ng <b>&amp;</b> Inte	rmediate None Cas	ing Ø Bradenl	head_ <del>O</del>
OPEN BRADENH	EAD AND INTERMEI  PRESSURES: EAD INTERMEDIATE	CASING	IMOSPHERE INDIV	BRADENHEAD	5 MINUTES EACH INTERMEDIATE FLOWED
5 minutes	NONE	-0	Steady Flow	· · · · · · · · · · · · · · · · · · ·	
10 minutes			Surges		
15 minutes			Down to Nothin	ng	
20 minutes			Nothing		NONE
25 minutes			Gas		
30 minutes			Gas & Water_		
			Water		
[f bradenhead flowed	water, check all of the d	escriptions tha			All Marie Species Commence of the Commence of
CLEARFRESHSALTYSULFUR				CK	
÷					Section 1 (1) and the section of the
	BRADENHEAD	I	NTERMEDIATE	<del></del>	
REMARKS:					
					April 14 Comments
3y (Fitt)	Thine		Witness		
Pumpe		<del></del>			
(Position)	7	<del></del>			
3-mail address					