



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-8178  
FAX: (505) 334-8170  
www.emnrd.state.nm.us/ocd/District3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 12-8-04 Operator BC+D Operating API #30-0 31-20800

Property Name Bank Fe RR "A" Well No. 96 Location: Unit 0 Section 1 Township 17<sup>N</sup> Range 9<sup>W</sup>

Well Status (Shut-In or Producing) Producing Tubing 90<sup>th</sup> Intermediate none Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>None</u>	<u>0</u>	Steady Flow	
10 minutes				Surges	
15 minutes				Down to Nothing	
20 minutes			<u>0</u>	Nothing <u>✓</u>	<u>None</u>
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN BRADENHEAD      INTERMEDIATE     

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By [Signature]

Witness \_\_\_\_\_

Pumper  
(Position)

E-mail address \_\_\_\_\_