



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-10-05 Operator Merrion Oil & Gas Corp. API #30-039-27563

Property Name Blueberry Buckle Com Well No. 002 Location: Unit K Section 32 Township 30N Range 07W

Well Status (Shut-In or Producing) Tubing 40 Intermediate Casing 115 Bradenhead 13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>			Steady Flow	
10 minutes	<u>0</u>			Surges	
15 minutes	<u>0</u>			Down to Nothing <input checked="" type="checkbox"/>	
20 minutes				Nothing	
25 minutes				Gas <input checked="" type="checkbox"/>	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 13 INTERMEDIATE

REMARKS:



By Frank Hancock

Witness

(Position)

Pumper

E-mail address