



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

RCVD NOV 15 '12

OIL CONS. DIV.

DIST. 3

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 11-15-12 Operator Chuzza Oil Co. API # 30-0 45-09653

Property Name NE Hogback Lt Well # 37 Location: Unit P Sec 10 Twn 30 Rge 16

Land Type:

State _____
Federal /
Private _____
Indian _____

Well Type:

Water Injection /
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. _____ Tbg. Inj. Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Pressured annulus up to 867 psi. for 30 mins. Test passed / failed

REMARKS:

Top Plug - 1688 Packer Set 1657
Rose to 900 lbs - good for last 8 min
Continue Ann

By PATRICK PADILLA
(Operator Representative)

Witness Monica Kuehling
(NMOCD)

PRESIDENT, CHUZA OIL
(Position)

Re-test in 1 year.

Revised 02-11-02